



Basement Band Joist Bottom Of Stair



Infrared Image



Visual Image

Voice Comment	
---------------	---

Analyses Table:

Object Parameter	Value
Max	56.2°F

Comments: Significant air infiltration at basement band joist.