



Right Side Of House



Infrared Image



Visual Image

Voice Comment	
---------------	---

Analyses Table:

Object Parameter	Value
Max	-1.6°F

Comments: Significant heat loss from basement band joist @ mechanical room.